iTero Packaging Instructions



Required parts

Foam Base



Wood Pallet







Wand Box

Wand Thermal Cover

Scanner Foam Support







Tube Set


Monitor Package


External Carton Box & Cover













Insert system into foam base.





Insert foam shelf support onto keyboard.























Place foot pedal in base at the front of the cart.





Insert the monitor into a plastic bag and place the original foam supports on monitor as shown.





Place monitor box over the screen.





Insert support poles









Assemble top cover.







Strap scanner to wood pallet

